


- Weekly performance
- Reduced intensity for cooldown before shutdown
- F27 water skid.
- 25.8 e-6 production efficiency with 6e12 on target.
- 6



o 20% less beam on target, 10% less stacking

- Last Week
 - Prior to Debuncher
 - D:H717 PS
 - LCW leak rate
 - Debuncher
 - D:ISEP
 - D:ISEP spare update
 - DRF1-5 Not doing well, turned down yet again this morning. Goes for a few hours and then trips.
 - □ Looks like PA tube problem
 - □ If downtime, will look at driver.
 - D:IB
 - □ 3 minute excursion.
 - D/A
 - Accumulator
 - A:IKIK HV and vacuum
 - □ 60KV with only minor burps.
 - 4-8GHz Kicker Tank update
 - □ Was able to recover the second tank.
 - □ Made sure water integrity was good.
 - □ Good
 - Transfers
 - AP1 wall current monitor -
 - Looking at optics There may be a bad magnet in the P1 line.
 - General
 - Documentation

Tours

- Tours
 - o <u>Draft Tour Schedule</u>
 - 1300-1700 Wed Jun 24 Dzero Workshop (4x25)
 - 1030-1300 Sat Jul 11 Ask-a-Scientist/PUBLIC (120)
 - 1300-1430 Thu Jul 16 Docents (~20)
 - 1300-1400 Fri Jul 17 Summer Students (25)
 - 1600-1730 M/T Jul 20/21 Quarknet Teachers (20?)
 - 1300-1400 Fri Jul 31 Summer Students (25)
 - 1030-1300 Sat Aug 8 Ask-a-Scientist/PUBLIC (120)
 - 0
- Shutdown
 - Stacking off 2200 Friday
 - Al will do tunes across the aperture Friday evening
 - Jim will do shunt tests Saturday morning.
 - Obie does lockout Sunday
 - o RWPs in huddle -
- a